

महाराष्ट्र शासन
उपविभागीय अभियंता यांचे कार्यालय
सा.बां.उपविभाग क्र.१ रत्नागिरी,
रत्नागिरी ४१५६१२ ☎ (०२३५२) २२२९२६

जा.क्र.उरवि/सा.बां./रत्ना-1 2020

दिनांक :- १७/१०/२०१८

To,
Principal
Jindal Vidya Mandir,
DM-4,JSW Township,
At-Chaferi,Post-Jaigad
Tal &Dist: Ratnagiri

BUILDING SAFETY CERTIFICATE

Ref No. : 1) Jindal Vidya Mandir letter No.JVM/2018-19/122 dtd 25.07.2018.
2) Executive Engineer ,Ratnagiri north office Letter.NRD/DB/DM/ Certificate/7762
dated 15 Oct 2018.

This is to certify that the existing school building of Jindal Vidya Mandir School located at JSW Township, At-Chaferi,Post-Jaigad, Tal and Dist-Ratnagiri has been inspected by me on 25th August 2018 for G+2 floors building on the basis of the drawings, designs prepared by Kadri Consultant Pvt.Ltd,Mumbai and Certificate of Stability of Structural given by Dr.Jaswant N. Arlekar Chartered Engineer from R. S. Mandarekar Mumbai.

The Building is in good and safe condition to run the school.

Follow below mentioned points to keep building in safe condition.

- 1) Work to be done by M/s. Arwade infrastructure Ltd. Pune as per National Building work standards.
- 2) As per certificate dated 01 jun 2015 given by consultant and chartered engineer Dr.JaswantN. Arlekar to take care of RCC object at the time of building maintenance, repair and building renovation. Thus , take precautions regarding not storing heavy items or materials in school building.
- 3) In emergency for immediate exit to students, keep passages hurdles less and display map of emergency exist in every class room.
- 4) Fire extinguishers installed for Fire fighting which are regularly checked and refilled or replaced with new one.
- 5) Leakage from any part of building especially Toilets, Pantry repair time to time and keep building leakage proof.


Sub-Divisional Engineer
P.W.D Sub Division No.1
Ratnagiri