

## To whom it may concern

It is certified that the building in which the Jindal Vidya Mandir School at Chholtu Distt. Kinnaur (HP) is running the building has been inspected by the Assistant Engineer HP PWD Sub-Division Tapri alongwith Junior Engineer HP PWD Section Tapri on dated 31<sup>st</sup> July,2023. The building consists of Three Story frame structure. The department has never inspected the building during its construction as the ownership of the building pertains to some other organization. The hidden items, like cement, steel foundation depth, quantity & quality etc. so used in the building are not known to this Department.


However by the visual inspection the building seems to be safe in normal loading conditions and no visual cracks etc. has been observed in the above said building.

It is further added that this Department holds no responsibility for damage to the above building in case of any natural calamities or building failure due to any structural failure.

**Note :- This Certificate is valid for a period of one year from date of issue.**

Date:- 31<sup>st</sup> July,2023

  
Junior Engineer  
Section Tapri  
HPPWD Tapri

  
Assistant Engineer  
Karchham Sub-Division  
HPPWD Tapri

  
Executive Engineer  
Karchham Division H.P.P.W.D.  
Karchham at Bhaba Nagar