

To whom it may concern

It is certified that, the building in which the Jindal Vidya Mandir School at Chholtu Distt. Kinnaur (H.P.) is operating has been inspected by the Assistant Engineer HPPWD Sub-Division Tapri along with Junior Engineer HPPWD Section Tapri on dated 16/12/025. The building consists of Four-Story frame structure. The department never inspected the building during its construction, as the ownership of the building belongs to another organization. Consequently, the hidden aspects, such as cement, steel, foundation depth, quantity and quality used in the building are unknown to this department.


However, based on visual inspection, the building appears to be safe under normal loading conditions, and no visible cracks etc. have been observed.


It is further stated that this department holds no responsibility for any damage to the aforementioned building in the event of any natural calamities or structural failure.

Note: This certificate is valid for a period of one year from date of issue.

Date: 16/12/025


Junior Engineer
Section Tapri


Assistant Engineer
Karchham Sub Division
HPPWD Tapri


Executive Engineer
Karchham Division
HPPWD Bhabanagar