


To whom it may concern


It is certificate that the building in which the Jindal Vidya Mandir School at Chholtu is running the building has been inspected by Assistant Engineer Tapri in dated 16 may 2020 along with JE Sh. Vivek Kumar. The building consists of Three story frame structure complete in all respect (Drawing of Building attached 4 pages). The department has never inspected the building during its construction as the building's owner ship pertains to some other Organization. The hidden items cement, steel, foundation depth quantity and quality so used are not known to department.


However by visual inspection the building seems to be safe in normal loading conditions.

It is further added that the department holds no responsibility in case of natural calamities i.e. earthquake floods. Unequal settlement.

Note: - This certificate is valid for a period of one year from date of issue


Junior Engineer
Karchham Sub Division
HPPWD Tapri


Assistant Engineer
Karchham Sub Division
HPPWD Tapri


Executive Engineer
Karchham Division
HPPWD Bhabanagar